

NEXINEO

# **NEXI GO SERVER PACKAGING INSTRUCTIONS FOR TRANSPORT**

## Warning!

During the transportation of packages by post and courier companies, the NEXI GO server may be damaged if improperly packaged, and therefore we recommend paying close attention to its packaging.

**The NEXI GO server contains a number of components that can be damaged if handled carelessly, therefore it is necessary to protect these components from damage, especially during transport.**

We recommend using the original packaging materials to pack the NEXI GO server. If you no longer have them available, we can send them to you upon request.

**Always send the NEXI GO server carefully packaged, insured and marked as fragile!**

**Mechanical damage caused during transport is not covered by the warranty!**

If you receive a package with damaged packaging (when returning the server), you must write a **damage report** before takeover, without which it will not be possible to claim insurance compensation in the event of damage to components.

We do not recommend packing the package in stretch film, as this film makes it impossible to see damage to the box.

**We recommend that you insure the package for a sufficient amount.**

### REQUIRED MATERIAL


To safely pack the NEXI GO server, you will need the following materials:

- NEXI GO server box
- Polystyrene covers
- PE foam sheets
- Bubble wrap
- Safety stickers



## INSERTING THE FILLING MATERIAL INTO THE NEXI GO SERVER

1. Carefully place the NEXI GO server in a horizontal position with the motherboard facing down.



2. Pull the marked bracket to fold out and remove the side panel.



3. This is what an open server looks like (according to the specification).



4. Carefully fill the gaps with non-conductive insulating material – we recommend bubble wrap.



5. Reinstall the side panel, first inserting the brackets at the bottom of the side panel into the marked holes.



6. Close the server by pressing the side panel at the top.



## PACKING THE NEXI GO SERVER INTO A BOX

1. Install the polystyrene covers on the NEXI GO server. Polystyrene marked TOP on the top side and BOTTOM on the bottom side of the server.



2. Place the box on the server.



3. This is what the server looks like in the box.



4. After placing the NEXI GO server in the box, label **the box** with “THIS SIDE UP” stickers. Stick the labels on the box according to the orientation of the server in the box. Apply the sticker so that the NEXI GO server motherboard is facing down.





5. Fill the gaps with PE foam.



6. Close the box and tape it with adhesive tape with an overlap of approximately 15 cm over the edge.



## FINALIZING THE PACKAGING

Fold the adhesive tape over two more layers of tape side by side.



Tape the box with adhesive tape around the perimeter and perpendicularly.



Stick a **FRAGILE** sticker on the top of the box. We **do not** recommend wrapping the box in stretch film.



## CONTACT INFORMATION

[support@nexineo.com](mailto:support@nexineo.com)

[shop.nexineo.com](http://shop.nexineo.com)